Thursday, 22/11/2007 12:57:21 PM User: Linda Lacelle **Process Sheet** : CC-DAR01 Dart Aerospace Ltd. Customer **Drawing Name** : REWORK : 35962 -2 Job Number : 10804 **Estimate Number** NA Part Number : D2807041 P.O. Number : 22/11/2007 This Issue S.O. No. : NA **Drawing Number** : ECN 1019 Prsht Rev. Project Number : SMALL /MED FAB First Issue Type **Drawing Revision** : 35961 Previous Run Material Each Qty: Due Date Written By Checked & Approved By Comment Additional Product Job Number: Seq. #: Description: Machine Or Operation: PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 REMOVE FROM STOCK: D2807 B 333941 SMALL FAB 1 2.0 SMALL & MEDIUM FAB RESOURCE 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 ADD D3671-1 PLACARD B 35613 TO D2807 (BECOMES D2807-041) PER DRWG D2807-041 3.0 D2807 Gas Spring (Support Prop) Comment: Qty.: 1.0000 Each(s)/Unit Total: 50.0000 Each(s) 33 94 Gas Spring (Support Prop) 4.0 D36711 Comment: Qty.: 1.0000 Each(s)/Unit Total: 50.0000 Each(s) **PLACARD** 5.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP

Date: User: Thursday, 22/11/2007 12:57:21 PM

Linda Lacelle

**Process Sheet** 

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: REWORK

Job Number: 35962

Part Number: D2807041

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

PACKAGING 1

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

RESTOCK USING NEW B/N

Job Completion



QC 21 Final w/o inspection A U BA.U.24

